	ICT OF SQUAMISH																				
	2021 FINANCIAL PLAN AL PLAN - GENERAL FUND																				
CALIT	Projects carrying forward from 2016									Sum	mary Of Funding	Over The Five	Year Plan			And Provisions		Key 2017/2018 Fund	ding Sources		
																				1	2018 Fund
Pof	Project	Total Cost	2017 Budget	2018 Budget	2019 Budget	2020 Budget	2021 Budget	Accum Surplus or Provision	Borrowing	Approved Borrowing	New Borrowing	Reserve	(Dev Front End)	DCC	Fund From Revenue	2017 Surplus Draw	2018 Surplus Draw	New Borrowing 2017	New Borrowing 2018	2017 Fund From Operating	From Operating
General C	Government	Total cost	zor, baaget	zolo baaget	2013 Budget	Zozo budget	Local budget	1100131011	Domowing	Dorrowing	Donowing	Reserve	(Best Holle Ella)	Dec	nevenue	2.0	5.0	2027	2020	operug	operating
	Real Estate																				
1	Forestry Building- New Roof  Corporate All	775,000		775,000				-	-	-	775,000	-		-	<u> </u>				775,000		
	Fleet Replacement - Prius (V9428)	28,000				28,000	)	-	- 1	-	-	28,000	-	-	-						
	Information Technology	803,000	=	775,000	-	28,000	-	-	-	-	775,000	28,000	-	-	-	-	-	-	775,000	-	-
2	Information Technology  Technology Transformation - Municipal ERP System	2,975,000	1,320,000	580,000	460,000			-	- 1	995,000	1,365,000	-	- 1	-				325,000	580,000	<del></del>	
3	Annual Workstation Upgrades	200,000	30,000	30,000	30,000		30,000	-	-	-	-	-	-	-	150,000				,	30,000	30,000
5	Large Format Printer/Scanner Replacement Webcam Upgrades	19,000 8,000	19,000 8,000					-	-	-	-	-	-	-	19,000 8,000					19,000 8,000	
-	Radio Tower Replacement	150,000	8,000		150,000			-	-	-	-	-		-	150,000					8,000	
		3,352,000	1,377,000	610,000	640,000	30,000	30,000	-	-	995,000	1,365,000	-		- '	327,000	-		325,000	580,000	57,000	30,000
6	Library  Space Improvements to Public Area of Library	25,000	<del>                                     </del>	25,000	Τ		1	-		. 1	. 1	_	т . т	-	25,000			1			25,000
	Library Roof and HVAC Replacement	550,000		23,000		550,000	)	-	-	-	550,000	-	-	-	-						20,000
	Replacement of Public Internet Computers	20,000		2- 222		20,000		-	-	-	-	-	-	-	20,000						25.000
7-4-10	cord Coursesset	595,000	- - 1 277 000	25,000	÷ 640,000	570,000			-	- c 005 000	550,000	- c 20,000	-	-	45,000			- -	- 4 2 - 2 - 2 - 2	- . c	25,000
	neral Government e Services	\$ 4,750,000	\$ 1,377,000	\$ 1,410,000	\$ 640,000	\$ 628,000	30,000	\$ -	\$ -	\$ 995,000	\$ 2,690,000	\$ 28,000	\$ - \$	-	\$ 372,000	\$ -	\$ -	\$ 325,000	\$ 1,355,000	\$ 57,000	\$ 55,000
	Police Services Facilities																				
7	RCMP - Exterior Camera System Upgrade (CF)  RCMP HVAC Replacement	17,500 125,000	17,500	-	50,000	75,000	-	10,000	-	-	-			-	7,500 125,000		0	1	1	7,500	
	RCMP HVAC Replacement RCMP Backup Generator	100,000			50,000	100,000			-	-	-		-	-	100,000						
		242,500	17,500	-	50,000	175,000	-	10,000	-	- '	- '	-		-	232,500	10,00	0 -	-	-	7,500	-
8	Fire Services Operations and Facilities  Tantalus Firehall Seismic Upgrade (CF)	2,000,000	1,791,136		_		T -	-		1,791,136	- 1	_	т . т				1	1			
9	Aerial Apparatus Scheduled Replacement	1,200,000	500,000	700,000		-	-	-	-	-	500,000	645,804	-	-	54,196			500,000			54,196
10		330,000	330,000	-	-	-	-	-	330,000	-	-	-	-	-	-						
11		325,000 160,000	320,893 160,000					-	-	320,893	-	-	-	-	160,000	1				160,000	
13	Tantalus Firehall Overhead Door Replacement	60,000	60,000					-	-	-	-	-	-	-	60,000					60,000	
14 15	Fire Training Centre Search Building Fire Department Pick up (7022) Replacement	30,000 34,500	-	30,000 34,500	-	-	-	-	-	-	-	30,726	10,000	-	20,000 3,774					<b></b>	20,000 3,774
16	Fire Department Auto Extrication Equipment	92,000	-	15,000	45,000			-	-	-	-	-	-	-	92,000					-	15,000
	Tantalus Firehall Office Roof Replacement	440,000			440,000	+		-	-	-	440,000	-	-	-	-						
_	Tantalus Firehall Windows and Doors Fleet replacement - Chev Silv (Chief 1)	60,000 27,000			60,000		27,000	-	-	-	-	27,000		-	60,000	1				<del> </del>	
	recereplacement energy (energy	4,758,500	3,162,029	779,500	545,000	32,000		-	330,000	2,112,029	940,000	703,530		-	449,970	-	-	500,000	-	220,000	92,970
47	Bylaw Enforcement & Facilities	T 50,000			1		1					27.704			42.000		1	1		T 42.200	
18	Fleet replacement- Animal Control Van (F9211)  Resolution Way Compound	50,000 20,000	50,000 20,000					-	-	-	-	37,701	-	-	12,299 20,000					12,299 20,000	
	Fleet replacement- Smart Car (V9427)	17,000				17,000		-	-	-	-	17,000		-	-						
	Emergency Management	87,000	70,000	-	-	17,000		-	-	•	•	54,701	-	•	32,299	-	-	-	-	32,299	-
19		40,000	40,000					-	-	-	-	40,000	-	-	-						
	Fleet replacement - F150 (Sep 10)	34,500				34,500		-	-	-	-	34,500		-	-						
T-4-I Du-	Anathur Comition	40,000	40,000			34,500		- 10.000	- 4 220 000			74,500 \$ 832,731		-					-	\$ 259,799	
i otai Pro	tective Services	\$ 5,162,500	\$ 3,289,529	\$ 779,500	\$ 595,000	\$ 258,500	) \$ 27,000	\$ 10,000	\$ 330,000	\$ 2,112,029	\$ 940,000	\$ 832,/31	\$ 10,000 \$	-	\$ 714,769	\$ 10,00	U \$ -	\$ 500,000	\$ -	\$ 259,799	\$ 92,970
Transpor	tation and Transit																				
	Flood Protection						. 1	-		-	-	-	-	-	-		1	1			
20	Dike Upgrades (CF) Dike / Xwu'nekw Park	10,750,000 4,600,000	2,350,000	2,100,000	2,100,000 500,000			-	-	-	3,750,000 4,600,000	-	7,000,000	-	-			950,000	700,000	+	
		15,350,000	2,350,000	2,100,000					-	- '	8,350,000	-	7,000,000	-	-	-	-	950,000	700,000	-	-
	Roads and Paving	4 473 050	1 172 050										630.654	F34.440	40.000		1			10.000	
21		1,172,856 4,800,000	1,172,856 800,000	1,000,000	1,000,000	1,000,000	1,000,000	-	-	-	-	-	628,651	534,119	10,086 4,800,000			+	+	10,086 800,000	1,000,000
23	Cleveland-Victoria To Main Streetscape upgrades	1,019,372	450,000					-	-	-	450,000	-	-	-	-			450,000			
24		1,000,000	200,000	200,000	200,000	· · · · · ·	200,000	-	-	-	-	-	870,000	-	130,000					26,000	26,000
25 26		75,000 81,000	25,000 27,000	25,000 27,000	25,000 27,000			-	-	-	-	-		-	75,000 81,000					25,000 27,000	25,000 27,000
27	DCC- R15- Garibaldi/Tantalus Signal	250,000	-	25,000	225,000			-	-	-	-	-	-	113,850	136,150						13,615
_	Brennan Park Paving (Future Project)	1,000,000			500,000	500,000	)	-	-	-	-	-	-	-	1,000,000	1				<b></b> '	
-		1																1	1	+	
		9,398,228	2,674,856	1,277,000	1,977,000	1,700,000	1,200,000	-	-	I	450,000	-	1,498,651	647,969	6,232,236	-	-	450,000	-	888,086	1,091,615
_	Alternative Transportation & Transit				1																
28 29		4,151,054 48,000	700,000 48,000	700,000	700,000	700,000	700,000	-	-	-	-	-	900,000	-	2,600,000 48,000			+	1	200,000 48,000	400,000
30		26,379	26,379					-	-	-	-		26,379	-	48,000			1	1	46,000	
31	Trails & Sidewalks Maintenance Machine	210,000	210,000					-	-	-	-	-	210,000	-	-						
32	Airport Runway Rehabilitation	720,000 <b>5,155,433</b>	984,379	720,000 <b>1,420,000</b>	700,000	700,000	700,000	105,000 105,000	-	-	-	-	540,000 <b>1,676,379</b>	-	75,000 2,723,000		105,000 105,000		1	248,000	75,000 <b>475,000</b>
	Drainage	3,133,433	304,379	1,420,000	700,000	700,000	, ,00,000	105,000	•	•	•	-	1,070,379	•	2,723,000	-	105,000		-	240,000	4/3,000

Part	021 FINANCIAL PLAN																			
Page																				
Part	Projects carrying forward from 2016									Sum	mary Of Funding	Over The Five	Year Plan			And Provisions		Key 2017/2018 Fund	ding Sources	
Part																				
March   Marc								•				_				1	1	_		
March   Marc	Project	Total Cost	2017 Budget	2018 Budget	2019 Budget	2020 Budget	2021 Budget	Provision	Borrowing	Borrowing	Borrowing	Reserve	(Dev Front End)	DCC	Revenue	Draw	Draw	2017	2018 Operating	
Part	Storm Sewer Condition Assessment/Flushing	400,000	-	100,000	100,000	100,000	100,000	-	-	-	-	-	-	-	400,000				-	
Mary	3rd Avenue Pond Remediation		-					-	-	-	,	-		-	-				· · · · · · · · · · · · · · · · · · ·	
Control   Cont		760,000	-	460,000	100,000	100,000	100,000	-	-	-	335,000	-	25,000	-	400,000	-	-	-	335,000 -	
Marie   Mari					1	1	1										1	1	T	
Marche   1968   1969	. 517		30,000					-	-	-		-	-	-					30,000	00
The state of the s	•			116,000	220,000			-	-	-		-	-		· · · · · · · · · · · · · · · · · · ·					+
STATE OF THE PARTY	Operations works fard - New Metal Roof		30,000	116 000				-								_		·	- 30,000	
The first property of	ation and Transit	400,000	30,000	110,000	320,000		<del>_</del>	<del>-</del>	<del>_</del>		320,000	<del>-</del>	<del>-</del>	<del>_</del>	140,000	-	<u> </u>		- 30,000	
Second Control   Seco								-	-	-	_	-	-	-	_					
The subsection of the property is a part o	· · · · · · · · · · · · · · · · · · ·	37,000	37,000					-	-	-	-	31,975	-	-	5,025				5,025	25
Marchester 167000000000000000000000000000000000000	Fleet Replacement- F150 (V9080)	37,000	37,000					-	-	-	-	31,170	-	-	5,830				5,830	30
March   Marc	Fleet Replacement- F150 (V9417)	37,000	37,000					-	-	-	-	27,630	-	-	9,370				9,370	70
The fine property of the control of								-	-	-	-		-	-						
Test Policy (1962)	. , ,		17,000					-	-	-	-		-	-					6,660	50
The Financial Control of Control	<u> </u>					ļ		-	-	-	-		-	-						$\dashv$
Manufact M						ļ	-	-	-	-	-		-	-	1		1	-	+ +	+
Description of the content of the			<del>                                     </del>			1		-		-	-		-	-			+		+ + + + + + + + + + + + + + + + + + + +	$\dashv$
Mile	<u> </u>			34,500	35 000	<del> </del>		-	-	-	-			-	· · · · · ·		+		+ +	$\dashv$
The following state of the control o	<u> </u>					1								-						+
The Management and performs    10						1		-							1				+ +	$\dashv$
The Programme of Control (Control (Co						<del> </del>		-			-	· · · · · · · · · · · · · · · · · · ·		-						$\dashv$
Mile					3.,330			-	-	-	-		-	-				1	<del>                                     </del>	$\dashv$
Mathematic and properties   1,000						· · · · · · · · · · · · · · · · · · ·		-	-	-	-		- 1	-	<u> </u>					$\dashv$
Marie National Processor   1968   1968   1969   1	Fleet Replacement - G3 Pontiac (V9435)	21,000				21,000		-	-	-	-	18,260	-	-	2,740					
Manual Process	Fleet Replacement - F350 (V9086)	36,000					36,000	-	-	-	-	36,000	-	-	-					
Marchine of Truits   1,000	Fleet Replacement - Escape (V9433)	36,000					36,000	-	-	-	-	36,000	-	-	-					
## Company Agency   Com	Fleet Replacement - Ford Escape (V9434)	26,000					26,000	-	-	-	-	25,770	-	-	230					
Method control control product inchose   1,000	sportation and Transit	\$ 32,037,661	\$ 6,204,235	\$ 5,512,500	\$ 5,916,500	\$ 8,986,000	\$ 4,198,000	\$ 105,000	\$ -	\$ -	\$ 9,455,000	\$ 669,099	\$ 10,200,030 \$	\$ 647,969	\$ 9,740,137	\$ -	\$ 105,000	\$ 1,400,000	) \$ 1,035,000 \$ 1,199,771	71
An Account Duty to Management (1968) (1968) (1969)	and Community Development								\$ -	\$ - -	\$ 9,455,000	\$ 669,099	\$ 10,200,030 \$	\$ 647,969				\$ 1,400,000		
A 1,000   1,00	and Community Development  Community Wayfinding Project  Entrance Sign	1,275,000	221,500	175,000				171,500	\$ - -	\$ - -	\$ 9,455,000	\$ 669,099	\$ 10,200,030 \$	\$ 647,969	1,000,000	171,500	1	\$ 1,400,000		
1,4150   15,050   2	and Community Development  Community Wayfinding Project  Entrance Sign  Adventure Center - Garbage Bin Enclosure	1,275,000 50,000 15,000	221,500	175,000 30,000				171,500	\$ - - -		-	\$ 669,099	\$ 10,200,030 \$	\$ 647,969 - - -	1,000,000 30,000 15,000	171,500	1	\$ 1,400,000	50,000	00
The stand Community Development (1978) (1978	And Community Development  Community Wayfinding Project  Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center- Exterior wood Staining	1,275,000 50,000 15,000 40,000	221,500 20,000 15,000	175,000 30,000		250,000		171,500	-		-	\$ 669,099 - - - -		-	1,000,000 30,000 15,000 40,000	171,500	1	\$ 1,400,000	50,000	00
Reference of Control Register (Register (Regis	And Community Development  Community Wayfinding Project  Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center- Exterior wood Staining	1,275,000 50,000 15,000 40,000 43,000	221,500 20,000 15,000	175,000 30,000 40,000	250,000	250,000 43,000	275,000	171,500 20,000 - -	-						1,000,000 30,000 15,000 40,000 43,000	171,500 20,000			15,000	00
Reference of Control Register (Register (Regis	And Community Development  Community Wayfinding Project  Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center- Exterior wood Staining	1,275,000 50,000 15,000 40,000 43,000	221,500 20,000 15,000	175,000 30,000 40,000	250,000	250,000 43,000	275,000	171,500 20,000 - -	-						1,000,000 30,000 15,000 40,000 43,000	171,500 20,000			15,000	00
## Provision Registering Plasman (152) (5)   175,00   175	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement	1,275,000 50,000 15,000 40,000 43,000 1,423,000	221,500 20,000 15,000 - - 256,500	175,000 30,000 40,000 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000   191,500			-			-	1,000,000 30,000 15,000 40,000 43,000 1,085,000	171,500 20,000 191,500	-	-	50,000 15,000	00
BP Area la Resultance Registrace (153)(C)	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development	1,275,000 50,000 15,000 40,000 43,000 1,423,000	221,500 20,000 15,000 - - 256,500	175,000 30,000 40,000 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000   191,500			-			-	1,000,000 30,000 15,000 40,000 43,000 1,085,000	171,500 20,000 191,500	-	-	50,000 15,000	00
## Area make tyg generator replacement   115,000   115,000   75,00	and Community Development  Community Wayfinding Project Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  of Parks and Culture	1,275,000 50,000 15,000 40,000 43,000 1,423,000	221,500 20,000 15,000 - - 256,500	175,000 30,000 40,000 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000   191,500			-			-	1,000,000 30,000 15,000 40,000 43,000 1,085,000	171,500 20,000 191,500	-	-	50,000 15,000	00
First Replacement: Demain Pale Frost FreeStart Van (F7098)	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  parks and Culture Recreation Facilities & Equipment	1,275,000 50,000 15,000 40,000 43,000 1,423,000 \$ 1,423,000	221,500 20,000 15,000 - 256,500 \$ 256,500	175,000 30,000 40,000 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000   191,500			-			-	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000	171,500 20,000 191,500	-	-	- 65,000 \$ - \$ 65,000	00 00 00 00
First Replacement: Demain Pale Frost FreeStart Van (F7098)	and Community Development  Community Wayfinding Project  Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center- Exterior wood Staining  Arts Council Building Roof Replacement  omic and Community Development  h, Parks and Culture  Recreation Facilities & Equipment  BP Arena Ice Resurfacer Replacement (8253) (CF)	1,275,000 50,000 15,000 40,000 43,000 1,423,000 \$ 1,423,000	221,500 20,000 15,000 256,500 \$ 256,500	175,000 30,000 40,000 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000   191,500			-			-	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000	171,500 20,000 191,500	-	-	50,000 15,000 - 65,000 \$ - \$ 65,000	00 00 00 00 00 00 00 00 00 00 00 00 00
BP-Fine Muchine	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment BP Arena Ice Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement	\$ 1,275,000 \$0,000 \$15,000 \$40,000 \$43,000 \$1,423,000 \$ 1,423,000 \$ 1,75,000 \$15,000 \$15,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 115,000	175,000 30,000 40,000 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000   191,500			-			-	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000	171,500 20,000 191,500	-	-	50,000 15,000 - 65,000 \$ - \$ 65,000	00 00 00 00 00 00 00 00 00 00 00 00 00
BP Area New Strip drain	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment BP Arena lce Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF)	1,275,000 50,000 15,000 40,000 43,000 1,423,000 \$ 1,423,000  175,000 115,000 75,000	221,500 20,000 15,000 - 256,500 \$ 256,500 175,000 115,000 75,000	175,000 30,000 40,000 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000   191,500			-	\$ -	\$ - \$	-	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000	171,500 20,000 191,500	-	-	50,000 15,000 - 65,000 \$ - \$ 65,000 20,350 115,000	000 000 000 000 000 000 000 000 000 00
Replace Infield Groomer Replace Contentions Re	and Community Development Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development a, Parks and Culture Recreation Facilities & Equipment BP Arena Ice Resurfacer Replacement (8253) (CF) BP Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates	\$ 1,423,000 \$ 1,423,000 \$ 1,423,000 \$ 1,5,000 \$ 1,423,000 \$ 1,5,000 \$ 1,5,000 \$ 1,5,000 \$ 1,5,000 \$ 25,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 115,000 75,000 60,000 25,000	175,000 30,000 40,000 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000   191,500			\$ -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000 24,825 25,000	171,500 20,000 191,500	-	-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 20,350 115,000	000   000
Replace Greenhouse 100,000 10,000 9,000 9,000 10,00	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development and Parks and Culture Recreation Facilities & Equipment BP Arena loc Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine	\$ 1,275,000 50,000 15,000 40,000 43,000 \$ 1,423,000 \$ 1,423,000 175,000 115,000 60,000 25,000 17,000	\$ 256,500 \$ 256,500 \$ 256,500 \$ 256,500 \$ 256,500 175,000 60,000 25,000 17,000	175,000 30,000 40,000 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000   191,500			\$ -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000 - 24,825 25,000 17,000	171,500 20,000 191,500	-	-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 20,350 115,000 24,825 25,000	000   000
Soot Replacement: Termenen Park Pump Nose   5,000	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment BP Arena Ice Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine BP Arena- New strip drain	\$ 1,275,000 50,000 15,000 40,000 1,423,000 \$ 1,423,000 \$ 1,423,000 175,000 115,000 60,000 25,000 17,000 16,500	221,500 20,000 15,000 256,500 \$ 256,500 175,000 115,000 75,000 60,000 25,000 17,000 16,500	175,000 30,000 40,000 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000   191,500			\$ -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000 24,825 25,000 17,000 16,500	171,500 20,000 191,500	-	-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 \$ 115,000 \$ 24,825 25,000 17,000	000 000 000 000 000 000 000 000 000 00
Campground Regulatory Improvements   10,000	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment BP Arena Ice Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine BP Arena- New Strip drain Replace Infield Groomer	\$ 1,275,000 \$50,000 \$15,000 \$43,000 \$1,423,000 \$ 1,423,000 \$ 175,000 \$15,000 \$15,000 \$15,000 \$17,000	221,500 20,000 15,000 - 256,500 \$ 256,500 175,000 60,000 25,000 17,000 16,500 16,500	175,000 30,000 40,000 245,000 \$ 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000 191,500 \$ 191,500			\$ -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000 - 24,825 25,000 17,000 16,500	171,500 20,000 191,500 \$ 191,500		-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 \$ 115,000 \$ 24,825 25,000 17,000	000 000 000 000 000 000 000 000 000 00
Septembry   172,500   1225,000   1225,000   1225,000   125,000	and Community Development  Community Wayfinding Project Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  a Parks and Culture Recreation Facilities & Equipment  BP Arena lce Resurfacer Replacement (8253) (CF)  BP Arena back up generator replacement  BP- Arena motor control center upgrade- Arena Slab (CF)  Fleet Replacement- Brennan Park Ford Freestar Van (F9083)  Senior center security gates  BP- Floor Machine  BP Arena- New strip drain  Replace Infield Groomer  Replace Greenhouse	\$ 1,275,000 \$0,000 15,000 40,000 1,423,000 \$ 1,423,000 \$ 1,423,000 \$ 1,5000 75,000 60,000 25,000 17,000 16,500 16,500 10,000	\$ 256,500 175,000 256,500 \$ 256,500 175,000 115,000 75,000 60,000 25,000 17,000 16,500 16,500 10,000	175,000 30,000 40,000 245,000 \$ 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000 191,500 \$ 191,500			\$ -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 40,000 1,085,000 \$ 1,128,000 \$ 1,128,000	171,500 20,000 191,500 \$ 191,500		-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 115,000 20,350 115,000 24,825 25,000 17,000 16,500 16,500	000 000 000 000 000 000 000 000 000 00
Seasobal Field Backstop & Dugout Replacement   100,000   .   25,000   25,	and Community Development Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development and Community Development by Parks and Culture Recreation Facilities & Equipment BP Arena Ice Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House	\$ 1,275,000 \$0,000 \$15,000 \$40,000 \$43,000 \$1,423,000 \$1,423,000 \$1,423,000 \$15,000 \$75,000 \$60,000 \$25,000 \$16,500 \$16,500 \$100,000 \$5,000	221,500 20,000 15,000 256,500 \$ 256,500 \$ 175,000 115,000 5,000 16,500 16,500 10,000 5,000	175,000 30,000 40,000 245,000 \$ 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000 191,500 \$ 191,500			\$ -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 40,000 1,085,000  \$ 1,128,000  \$ 20,350 115,000 24,825 25,000 17,000 16,500 90,000 5,000	171,500 20,000 191,500 \$ 191,500		-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 115,000 20,350 115,000 24,825 25,000 17,000 16,500 16,500 5,000	500   DOO
BP Community Centre Roof and HVAC Replacement 890,000   100,000	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment BP Arena Ice Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House Campground Regulatory Improvements	\$ 1,275,000 \$0,000 \$15,000 \$43,000 \$43,000 \$1,423,000 \$ 1,423,000 \$15,000 \$15,000 \$15,000 \$15,000 \$15,000 \$16,500 \$16,500 \$100,000 \$5,000 \$100,000 \$10,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 115,000 75,000 10,000 16,500 16,500 10,000 5,000	175,000 30,000 40,000 245,000 \$ 245,000	250,000 250,000	250,000 43,000 250,000	275,000	171,500 20,000 191,500 \$ 191,500			\$ -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000 - 24,825 25,000 17,000 16,500 16,500 90,000 5,000 10,000	171,500 20,000 191,500 \$ 191,500		-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 115,000 20,350 115,000 24,825 25,000 17,000 16,500 16,500 5,000	500   DOO
BP Community Centre Electrical Transformer  BP Arena Compressor and Motor  2,280,000 525,000 340,000 1,015,000 375,000 25,000 10,000 75,000 1,240,000 174,825 15,000 665,175 10,000 . 25,0175  Aparks, Trails and Park Facilities  Dentrylile Community Park  117,500 117,500 10,000 5,000 10,000 5,000 10,000 5,000 10,000 1	and Community Development  Community Wayfinding Project Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center - Exterior wood Staining  Arts Council Building Roof Replacement  omic and Community Development  In, Parks and Culture Recreation Facilities & Equipment  BP Arena Ice Resurfacer Replacement (8253) (CF)  BP Arena back up generator replacement  BP- Arena motor control center upgrade- Arena Slab (CF)  Fleet Replacement- Brennan Park Ford Freestar Van (F9083)  Senior center security gates  BP- Floor Machine  BP Arena- New strip drain  Replace Infield Groomer  Replace Greenhouse  Roof Replacement- Brennen Park Pump House  Campground Regulatory Improvements  BP- Arena Insulation	\$ 1,275,000 \$0,000 \$15,000 40,000 \$43,000 \$ 1,423,000 \$ 1,423,000 \$ 1,75,000 115,000 75,000 60,000 25,000 16,500 10,000 5,000 10,000 225,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 115,000 75,000 60,000 17,000 16,500 16,500 10,000	\$ 245,000 90,000	250,000 250,000 \$ 250,000	250,000 43,000 250,000 \$ 293,000	275,000 275,000 \$ 275,000	171,500 20,000 191,500 \$ 191,500			\$ -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 43,000 1,085,000 \$ 1,128,000 \$ 1,128,000  20,350 115,000 24,825 25,000 17,000 16,500 90,000 5,000 10,000 225,000	171,500 20,000 191,500 \$ 191,500		-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 115,000 20,350 115,000 24,825 25,000 17,000 16,500 16,500 5,000	500   DOO
B P Area Compressor and Motor 350,000   1,015,000   350,000   1,015,000   375,000   25,000   1,000   75,000   1,240,000   174,825   15,000   665,175   10,000   250,175   1,000   250,175   1,000	and Community Development  Community Wayfinding Project Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center - Exterior wood Staining  Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture  Recreation Facilities & Equipment  BP Arena Ice Resurfacer Replacement (8253) (CF)  BP Arena back up generator replacement  BP- Arena motor control center upgrade- Arena Slab (CF)  Fleet Replacement- Brennan Park Ford Freestar Van (F9083)  Senior center security gates  BP- Floor Machine  BP Arena- New strip drain  Replace Infield Groomer  Replace Greenhouse  Roof Replacement- Brennen Park Pump House  Campground Regulatory Improvements  BP- Arena Insulation  Baseball Field Backstop & Dugout Replacement	1,275,000 50,000 15,000 40,000 43,000 1,423,000 \$ 1,423,000  115,000 115,000 75,000 60,000 25,000 116,500 100,000 5,000 10,000 225,000 10,000 225,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 115,000 75,000 60,000 17,000 16,500 16,500 10,000	\$ 245,000 90,000	250,000 250,000 \$ 250,000	250,000 43,000 250,000 \$ 293,000	275,000 275,000 \$ 275,000	171,500 20,000 191,500 \$ 191,500			\$ -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 43,000 1,085,000 \$ 1,128,000 \$ 1,128,000  20,350 115,000 24,825 25,000 17,000 16,500 90,000 5,000 10,000 225,000	171,500 20,000 191,500 \$ 191,500		-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 115,000 20,350 115,000 24,825 25,000 17,000 16,500 16,500 5,000	00   00   00   00   00   00   00   00
Parks and Culture (continued) Parks Farilis and Park Facilities  Dentrille Community Park  Dent	and Community Development Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center - Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development and Community Development by Parks and Culture Recreation Facilities & Equipment BP Arena lace Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House Campground Regulatory Improvements BP- Arena Insulation Baseball Field Backstop & Dugout Replacement BP Community Centre Roof and HVAC Replacement	\$ 1,275,000 \$ 50,000 \$ 15,000 \$ 40,000 \$ 43,000 \$ 1,423,000 \$ 1,423,000 \$ 175,000 \$ 15,000 \$ 60,000 \$ 25,000 \$ 17,000 \$ 16,500 \$ 16,500 \$ 100,000 \$ 5,000 \$ 10,000 \$ 225,000 \$ 10,000 \$ 225,000 \$ 10,000 \$ 890,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 115,000 75,000 60,000 17,000 16,500 16,500 10,000	\$ 245,000 90,000	250,000 250,000 \$ 250,000 250,000 25,000 890,000	250,000 43,000 250,000 \$ 293,000	275,000 275,000 \$ 275,000	171,500 20,000 191,500 \$ 191,500			\$ -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 43,000 1,085,000 \$ 1,128,000 \$ 1,128,000  20,350 115,000 24,825 25,000 17,000 16,500 90,000 5,000 10,000 225,000	171,500 20,000 191,500 \$ 191,500		-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 115,000 20,350 115,000 24,825 25,000 17,000 16,500 16,500 5,000	500   100
Parks, Trails and Park Facilities  Dentyille Community Park  Dentyille Community Park  Dentyille Community Park  Denty Bernen Park Electrical Shed repairs  15,000  10,000  1	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center - Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment  BP Arena loce Resurfacer Replacement (8253) (CF)  BP Arena back up generator replacement  BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates  BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House Campground Regulatory Improvements BP- Arena Insulation Baseball Field Backstop & Dugout Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Roof and HVAC Replacement	\$ 1,275,000 \$ 50,000 \$ 15,000 \$ 43,000 \$ 1,423,000  \$ 1,423,000  \$ 175,000 \$ 175,000 \$ 60,000 \$ 25,000 \$ 17,000 \$ 16,500 \$ 16,500 \$ 100,000 \$ 225,000 \$ 10,000 \$ 225,000 \$ 10,000 \$ 225,000 \$ 10,000 \$ 225,000 \$ 10,000 \$ 205,000 \$ 10,000 \$ 205,000 \$ 100,000 \$ 205,000 \$ 100,000 \$ 205,000 \$ 100,000 \$ 205,000 \$ 100,000 \$ 205,000 \$ 100,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 115,000 75,000 60,000 17,000 16,500 16,500 10,000	\$ 245,000 90,000	250,000 250,000 \$ 250,000 250,000 25,000 890,000	\$ 250,000 \$ 293,000 \$ 250,000	275,000 275,000 \$ 275,000	171,500 20,000 191,500 \$ 191,500			\$ - - - - - - - - - - - - - - - - - - -	\$ -	\$ - \$	-	1,000,000 30,000 15,000 40,000 1,085,000 1,128,000 \$ 1,128,000  20,350 115,000 24,825 25,000 17,000 16,500 90,000 5,000 10,000	171,500 20,000 191,500 \$ 191,500		-	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 115,000 20,350 115,000 24,825 25,000 17,000 16,500 16,500 5,000	500   DOO
Dentylille Community Park   172,500   172,50	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center - Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment  BP Arena loce Resurfacer Replacement (8253) (CF)  BP Arena back up generator replacement  BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates  BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House Campground Regulatory Improvements BP- Arena Insulation Baseball Field Backstop & Dugout Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Roof and HVAC Replacement	1,275,000 50,000 15,000 40,000 43,000 1,423,000  \$ 1,423,000  175,000 60,000 25,000 17,000 16,500 10,000 5,000 10,000 100,000 100,000 100,000 100,000 100,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 60,000 17,000 16,500 16,500 10,000 10,000	175,000 30,000 40,000 245,000 \$ 245,000 90,000 225,000	250,000 \$ 250,000 \$ 250,000 \$ 25,000 890,000 100,000	\$ 293,000 \$ 293,000 250,000	275,000 275,000 \$ 275,000 25,000	171,500 20,000 191,500  \$ 191,500	\$ -	\$ - - - - - - - - - - - - - - - - - - -	\$ - - - - - - - - - - - - - - - - - - -	\$ - - - - - - - - - - - - - - - - - - -	\$ - \$	- - - - - - - - - - - - - - - - - - -	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000	171,500 20,000 191,500 \$ 191,500		\$ -	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 115,000 115,000 124,825 225,000 16,500 16,500 10,000	000 000 000 000 000 000 000 000 000 00
Brennen Park Electrical Shed repairs   15,000   10,000	and Community Development Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development n, Parks and Culture Recreation Facilities & Equipment BP Arena lce Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House Campground Regulatory Improvements BP- Arena Insulation Baseball Field Backstop & Dugout Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Electrical Transformer BP Arena Compressor and Motor	1,275,000 50,000 15,000 40,000 43,000 1,423,000  \$ 1,423,000  175,000 60,000 25,000 17,000 16,500 10,000 5,000 10,000 100,000 100,000 100,000 100,000 100,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 60,000 17,000 16,500 16,500 10,000 10,000	175,000 30,000 40,000 245,000 \$ 245,000 90,000 225,000	250,000 \$ 250,000 \$ 250,000 \$ 25,000 890,000 100,000	\$ 293,000 \$ 293,000 250,000	275,000 275,000 \$ 275,000 25,000	171,500 20,000 191,500  \$ 191,500	\$ -	\$ - - - - - - - - - - - - - - - - - - -	\$ - - - - - - - - - - - - - - - - - - -	\$ - - - - - - - - - - - - - - - - - - -	\$ - \$	- - - - - - - - - - - - - - - - - - -	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000	171,500 20,000 191,500 \$ 191,500		\$ -	\$ - \$ 65,000 \$ - \$ 65,000 \$ - \$ 65,000 115,000 115,000 124,825 225,000 16,500 16,500 10,000	000 000 000 000 000 000 000 000 000 00
Replacement of Parks Fertilizer Spreader  10,000	and Community Development Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  a Parks and Culture Recreation Facilities & Equipment BP Arena lce Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House Campground Regulatory Improvements BP- Arena Insulation Baseball Field Backstop & Dugout Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Electrical Transformer BP Arena Compressor and Motor  a Parks, Trails and Park Facilities	1,275,000 50,000 15,000 40,000 43,000 1,423,000  \$ 1,423,000  \$ 1,423,000  115,000 75,000 60,000 25,000 116,500 16,500 100,000 25,000 100,000 225,000 100,000 350,000 2,280,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 60,000 25,000 16,500 16,500 10,000 5,000	175,000 30,000 40,000 245,000 \$ 245,000 90,000 225,000	250,000 \$ 250,000 \$ 250,000 \$ 25,000 890,000 100,000	\$ 293,000 \$ 293,000 250,000	275,000 275,000 \$ 275,000 25,000	171,500 20,000 191,500 \$ 191,500	\$ -	\$ - - - - - - - - - - - - - - - - - - -	\$ - - - - - - - - - - - - - - - - - - -	\$ - - - - - - - - - - - - - - - - - - -	\$ - \$		1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  \$ 1,128,000	171,500 20,000 191,500 \$ 191,500	5 -	\$ -	50,000  15,000  - 65,000  \$ - \$ 65,000  20,350  115,000  24,825  25,000  17,000  16,500  5,000  10,000  - 250,175	500   D00
Tourism Access/ trailhead Improvements 75,000 -	and Community Development  Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment  BP Arena loce Resurfacer Replacement (8253) (CF)  BP Arena back up generator replacement  BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates  BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House Campground Regulatory Improvements BP- Arena Insulation Baseball Field Backstop & Dugout Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Roof and HVAC Replacement BP Arena Compressor and Motor  n, Parks and Culture (continued) Parks, Trails and Park Facilities Dentville Community Park	1,275,000 50,000 15,000 40,000 43,000 1,423,000 \$ 1,423,000  \$ 1,423,000  175,000 60,000 25,000 17,000 16,500 100,000 5,000 100,000 100,000 350,000 2,280,000 172,500	221,500 20,000 15,000 256,500 \$ 256,500 175,000 115,000 75,000 10,000 16,500 16,500 10,000 5,000 10,000	175,000 30,000 40,000 245,000 \$ 245,000 90,000 225,000 25,000	250,000 \$ 250,000 \$ 250,000 \$ 25,000 890,000 100,000	\$ 293,000 \$ 293,000 250,000	275,000 275,000 \$ 275,000 25,000	171,500 20,000 191,500 \$ 191,500	\$ -	\$ - - - - - - - - - - - - - - - - - - -	\$ - - - - - - - - - - - - - - - - - - -	\$ - - - - - - - - - - - - - - - - - - -	\$ - \$		1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000 24,825 25,000 17,000 16,500 16,500 90,000 5,000 10,000 665,175	171,500 20,000 191,500 \$ 191,500	5 -	\$ -	50,000  15,000  - 65,000  \$ - \$ 65,000  115,000  20,350  115,000  124,825  25,000  17,000  16,500  10,000  - 250,175	000   000
272,50 192,50 80,00 60,000 79,695 132,805 60,00 86,960 86,960 86,960 86,960 86,960 86,960 - 86,000 86,960 86,960 86,960 86,960 86,960 - 86,000 86,960 86,960 86,960 86,960 86,960 - 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 86,960 86,960 86,960 86,960 86,960 86,960 - 8	and Community Development  Community Wayfinding Project Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center- Exterior wood Staining  Arts Council Building Roof Replacement  omic and Community Development  In, Parks and Culture  Recreation Facilities & Equipment  BP Arena Ice Resurfacer Replacement (8253) (CF)  BP Arena back up generator replacement  BP- Arena motor control center upgrade- Arena Slab (CF)  Fleet Replacement- Brennan Park Ford Freestar Van (F9083)  Senior center security gates  BP- Floor Machine  BP Arena- New strip drain  Replace Infield Groomer  Replace Greenhouse  Roof Replacement- Brennen Park Pump House  Campground Regulatory Improvements  BP- Arena Insulation  Baseball Field Backstop & Dugout Replacement  BP Community Centre Roof and HVAC Replacement  BP Community Centre Roof and HVAC Replacement  BP Community Centre Roof and HVAC Replacement  BP Arena Compressor and Motor  In, Parks and Culture (continued)  Parks, Trails and Park Facilities  Dentville Community Park  Brennen Park Electrical Shed repairs	1,275,000 50,000 15,000 40,000 43,000 1,423,000 \$ 1,423,000  \$ 1,423,000  115,000 115,000 75,000 60,000 25,000 10,000 10,000 10,000 890,000 100,000 350,000 2,280,000 2,280,000	221,500 20,000 15,000 256,500 \$ 256,500 115,000 115,000 75,000 60,000 16,500 16,500 10,000 5,000 10,000 	175,000 30,000 40,000 245,000 \$ 245,000 90,000 225,000 25,000	250,000 \$ 250,000 \$ 250,000 \$ 25,000 890,000 100,000	\$ 293,000 \$ 293,000 250,000	275,000 275,000 \$ 275,000 25,000	171,500 20,000 191,500 \$ 191,500	\$ -			\$ - - - - - - - - - - - - - - - - - - -	\$ - \$	- - - - - - - - - - - - - - - - - - -	1,000,000 30,000 15,000 43,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000 24,825 25,000 17,000 16,500 90,000 5,000 10,000 665,175	171,500 20,000 191,500 \$ 191,500	5 -	\$ -	50,000  15,000  - 65,000  \$ - \$ 65,000  115,000  115,000  115,000  115,000  115,000  10,000  - 250,175	50   00   00   00   00   00   00   00
reation, Parks and Trails \$ 2,552,500 \$ 717,500 \$ 420,000 \$ 1,015,000 \$ 375,000 \$ 25,000 \$ 70,000 \$ - \$ 75,000 \$ 1,240,000 \$ 174,825 \$ 15,000 \$ 79,695 \$ 797,980 \$ 70,000 \$ - \$ - \$ - \$ - \$ 337,135 \$ 18th - Cemetery	and Community Development  Community Wayfinding Project Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center- Exterior wood Staining  Arts Council Building Roof Replacement  omic and Community Development  In, Parks and Culture  Recreation Facilities & Equipment  BP Arena Ice Resurfacer Replacement (8253) (CF)  BP Arena loce Resurfacer Replacement  BP- Arena back up generator replacement  BP- Arena motor control center upgrade- Arena Slab (CF)  Fleet Replacement- Brennan Park Ford Freestar Van (F9083)  Senior center security gates  BP- Floor Machine  BP Arena- New strip drain  Replace Infield Groomer  Replace Greenhouse  Roof Replacement- Brennen Park Pump House  Campground Regulatory Improvements  BP- Arena Insulation  Baseball Field Backstop & Dugout Replacement  BP Community Centre Roof and HVAC Replacement  BP Community Centre Roof and HVAC Replacement  BP Arena Compressor and Motor  In, Parks and Culture (continued)  Parks, Trails and Park Facilities  Dentville Community Park  Brennen Park Electrical Shed repairs  Replacement of Parks Fertilizer Spreader	1,275,000 50,000 15,000 40,000 43,000 1,423,000 \$ 1,423,000  \$ 1,423,000  115,000 115,000 115,000 75,000 60,000 25,000 100,000 10,000 10,000 225,000 100,000 225,000 100,000 225,000 100,000 225,000 110,000 225,000 110,000 225,000 110,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 60,000 25,000 16,500 16,500 10,000 5,000 10,000 	175,000 30,000 40,000 245,000 \$ 245,000 90,000 225,000 25,000	250,000 \$ 250,000 \$ 250,000 \$ 25,000 890,000 100,000	\$ 293,000 \$ 293,000 250,000	275,000 275,000 \$ 275,000 25,000	171,500 20,000 191,500 \$ 191,500	\$ -			\$ - - - - - - - - - - - - - - - - - - -	\$ - \$	- - - - - - - - - - - - - - - - - - -	1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000 \$ 1,128,000  20,350 115,000 24,825 25,000 17,000 16,500 90,000 5,000 10,000 665,175  66,960 15,000	171,500 20,000 191,500 \$ 191,500	5 -	\$ -	50,000  15,000  - 65,000  \$ - \$ 65,000  115,000  115,000  115,000  115,000  115,000  10,000  - 250,175	000 000 000 000 000 000 000 000 000 00
Alth - Cemetery  Cemetary Over-Excavation 65,000 65,000 65,000	and Community Development  Community Wayfinding Project Entrance Sign  Adventure Center - Garbage Bin Enclosure  Adventure Center- Exterior wood Staining  Arts Council Building Roof Replacement  omic and Community Development  In, Parks and Culture  Recreation Facilities & Equipment  BP Arena Ice Resurfacer Replacement (8253) (CF)  BP Arena loce Resurfacer Replacement  BP- Arena back up generator replacement  BP- Arena motor control center upgrade- Arena Slab (CF)  Fleet Replacement- Brennan Park Ford Freestar Van (F9083)  Senior center security gates  BP- Floor Machine  BP Arena- New strip drain  Replace Infield Groomer  Replace Greenhouse  Roof Replacement- Brennen Park Pump House  Campground Regulatory Improvements  BP- Arena Insulation  Baseball Field Backstop & Dugout Replacement  BP Community Centre Roof and HVAC Replacement  BP Community Centre Roof and HVAC Replacement  BP Arena Compressor and Motor  In, Parks and Culture (continued)  Parks, Trails and Park Facilities  Dentville Community Park  Brennen Park Electrical Shed repairs  Replacement of Parks Fertilizer Spreader	1,275,000 50,000 15,000 40,000 43,000 1,423,000  \$ 1,423,000  115,000 115,000 115,000 115,000 115,000 100,000 100,000 100,000 100,000 225,000 100,000 225,000 100,000 225,000 110,000 225,000 110,000 225,000 110,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 60,000 25,000 16,500 16,500 10,000 5,000 10,000 10,000	175,000 30,000 40,000 245,000 \$ 245,000 90,000 225,000 25,000 5,000	250,000 250,000 \$ 250,000 25,000 890,000 1,015,000	250,000 43,000 250,000 \$ 293,000 25,000 25,000 375,000	275,000 275,000 \$ 275,000 25,000	171,500 20,000	\$	\$ - - - - - - - - - - - - - - - - - - -		\$	\$ - \$		1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000  20,350 115,000 24,825 25,000 16,500 90,000 5,000 10,000 225,000 10,000 665,175	171,500 20,000 191,500 \$ 191,500 10,000	\$ -	\$ -	50,000  15,000  - 65,000  \$ - \$ 65,000  \$ 20,350  115,000  24,825  25,000  17,000  16,500  10,000  - 250,175	500   DO   DO   DO   DO   DO   DO   DO
Cemetary Over-Excavation         65,000         -         -         -         -         -         65,000	and Community Development Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment BP Arena Ice Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House Campground Regulatory Improvements BP- Arena Insulation Baseball Field Backstop & Dugout Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Roof and HVAC Replacement BP Arena Compressor and Motor  n, Parks, Trails and Park Facilities Dentville Community Park Brennen Park Electrical Shed repairs Replacement of Parks Fertilizer Spreader Tourism Access/ trailhead Improvements	1,275,000 50,000 15,000 40,000 43,000 1,423,000  \$ 1,423,000  115,000 115,000 115,000 75,000 60,000 25,000 100,000 10,000 225,000 100,000 225,000 100,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 2280,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 60,000 25,000 16,500 16,500 10,000 5,000 10,000 	175,000 30,000 40,000 245,000 \$ 245,000 90,000 225,000 25,000 5,000 75,000 80,000	250,000 \$ 250,000 \$ 250,000 \$ 250,000 890,000 100,000	250,000 43,000 250,000 \$ 293,000 25,000 350,000 375,000	275,000 275,000 \$ 275,000 25,000	171,500 20,000	\$	\$ - - - - - - - - - - - - - - - - - - -		\$ -	\$ - \$		1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000 \$ 1,128,000  \$ 20,350 115,000	171,500 20,000 191,500 \$ 191,500 10,000 10,000	\$ -	\$ -	50,000  15,000  - 65,000  \$ - \$ 65,000  115,000  115,000  115,000  115,000  10,000  - 250,175  66,960  10,000  - 86,960	000 000 000 000 000 000 000 000 000 00
	and Community Development Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment BP Arena Ice Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House Campground Regulatory Improvements BP- Arena Insulation Baseball Field Backstop & Dugout Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Roof and HVAC Replacement BP Arena Compressor and Motor  n, Parks, Trails and Park Facilities Dentville Community Park Brennen Park Electrical Shed repairs Replacement of Parks Fertilizer Spreader Tourism Access/ trailhead Improvements	1,275,000 50,000 15,000 40,000 43,000 1,423,000  \$ 1,423,000  115,000 115,000 115,000 75,000 60,000 25,000 100,000 10,000 225,000 100,000 225,000 100,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 2280,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 60,000 25,000 16,500 16,500 10,000 5,000 10,000 	175,000 30,000 40,000 245,000 \$ 245,000 90,000 225,000 25,000 5,000 75,000 80,000	250,000 \$ 250,000 \$ 250,000 \$ 250,000 890,000 100,000	250,000 43,000 250,000 \$ 293,000 25,000 350,000 375,000	275,000 275,000 \$ 275,000 25,000	171,500 20,000	\$	\$ - - - - - - - - - - - - - - - - - - -		\$ -	\$ - \$		1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000 \$ 1,128,000  \$ 20,350 115,000	171,500 20,000 191,500 \$ 191,500 10,000 10,000	\$ -	\$ -	50,000  15,000  - 65,000  \$ - \$ 65,000  115,000  115,000  115,000  115,000  10,000  - 250,175  66,960  10,000  - 86,960	000 000 000 000 000 000 000 000 000 00
lic Health - Cemetery \$ 65,000 \$ - \$ 65,000 \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	and Community Development Community Wayfinding Project Entrance Sign Adventure Center - Garbage Bin Enclosure Adventure Center- Exterior wood Staining Arts Council Building Roof Replacement  omic and Community Development  n, Parks and Culture Recreation Facilities & Equipment BP Arena Ice Resurfacer Replacement (8253) (CF) BP Arena back up generator replacement BP- Arena motor control center upgrade- Arena Slab (CF) Fleet Replacement- Brennan Park Ford Freestar Van (F9083) Senior center security gates BP- Floor Machine BP Arena- New strip drain Replace Infield Groomer Replace Greenhouse Roof Replacement- Brennen Park Pump House Campground Regulatory Improvements BP- Arena Insulation Baseball Field Backstop & Dugout Replacement BP Community Centre Roof and HVAC Replacement BP Community Centre Roof and HVAC Replacement BP Arena Compressor and Motor  n, Parks and Culture (continued) Parks, Trails and Park Facilities Dentville Community Park Brennen Park Electrical Shed repairs Replacement of Parks Fertilizer Spreader Tourism Access/ trailhead Improvements	1,275,000 50,000 15,000 40,000 43,000 1,423,000  \$ 1,423,000  115,000 115,000 115,000 75,000 60,000 25,000 100,000 10,000 225,000 100,000 225,000 100,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 110,000 225,000 2280,000	221,500 20,000 15,000 256,500 \$ 256,500 175,000 60,000 25,000 16,500 16,500 10,000 5,000 10,000 	175,000 30,000 40,000 245,000 \$ 245,000 90,000 225,000 25,000 5,000 75,000 80,000	250,000 \$ 250,000 \$ 250,000 \$ 250,000 890,000 100,000	250,000 43,000 250,000 \$ 293,000 25,000 350,000 375,000	275,000 275,000 \$ 275,000 25,000	171,500 20,000	\$	\$ - - - - - - - - - - - - - - - - - - -		\$ -	\$ - \$		1,000,000 30,000 15,000 40,000 43,000 1,085,000 \$ 1,128,000 \$ 1,128,000  \$ 20,350 115,000	171,500 20,000 191,500 \$ 191,500 10,000 10,000	\$ -	\$ -	50,000  15,000  - 65,000  \$ - \$ 65,000  115,000  115,000  115,000  115,000  10,000  - 250,175  66,960  10,000  - 86,960	000 000 000 000 000 000 000 000 000 00

Projects carrying forward from 2016									Sum	mary Of Funding	Over The Five	Year Plan		/	And Provisions		Key 2017/2018 Fund	Jing Sources		
Project	Total Cost	2017 Budget	2018 Budget	2019 Budget	2020 Budget	2021 Budget	Accum Surplus or Provision	Short Term Borrowing	Approved Borrowing	New Borrowing	Reserve	Grants & Other (Dev Front End)	DCC	Fund From Revenue	2017 Surplus Draw	2018 Surplus Draw	New Borrowing 2017	New Borrowing 2018	2017 Fund From Operating	201 n I Op
WPORT BEACH																				
			1				Accum Surplus or	Short Term	Approved	New			Developer	Fund From	2017 Surplus	2018 Surplus			2017 Fund From	
	Total Cost	2017 Budget	2018 Budget	2019 Budget	2020 Budget	2021 Budget	Provision	Borrowing	Borrowing	Borrowing	Reserve	Grants & Other	Contribution	Revenue	Draw	Draw	2017	2018	Operating	(
5		1		1	1	1		1	,		1									_
SODC- DCC- R20- Peninsula Main Road- Arterial Standard	8,200,000	2,634,439	2,730,000	1,365,000	1,365,000		_		_	4,408,231	_	_	3,686,208		· '		1,434,715	1,486,758	, 	
SODC- DCC- D15- Peninsula Shared Storm Water Mains	481,000	481,000		, ,			-	-	-	-	-	-	476,190	4,810					4,810	T
SODC- DCC- D13- Peninsula Treatment Wetland at Mamquam Blind Channel	260,000	260,000					-	-	-	-	-	-	257,400	2,600	<u> </u>				2,600	T
SODC- DCC- D14- Peninsula Treatment Wetland atRoad 'O'	260,000	260,000					-	-	-			-	257,400	2,600	<u>'</u>				2,600	T
SODC- DCC- R18- East Downtown Connector (Future Project)	3,750,000	-	-	375,000	3,375,000		-	-	-	1,838,025		-	1,707,750	204,225	·				1	T
	12,951,000	3,635,439	2,730,000	1,740,000	4,740,000		-	<u> </u>	<u> </u>	6,246,256	-	·	6,384,948	214,235	_		1,434,715	1,486,758	10,010	<u>;</u> =
		, ,	, ,	, ,,	, ,,					, , ,			7,1,7				, , , ,	, , , , ,		
SODC- DCC- P17- Oceanfront Boardwalk A & B	1,220,538		1,220,538				-	-	-	-	-	-	560,031	660,507						$\perp$
	1,220,538	-	1,220,538	-	-	-	-	-	-	-	-	-	560,031	660,507	-	-	-	-	-	_
neral Fund	14,171,538	3,635,439	3,950,538	1,740,000	4,740,000	-	-	-	÷	6,246,256	-	-	6,944,979	874,742	-	-	1,434,715	1,486,758	10,010	
		15,480,203	12,382,538									Target for Tax Use (Under)/Exceeded		1,756,895 161,810	1,918,705	411,810				
												(Under)/Exceeded	with SODC	171,820	1,928,715	421,820				

		Strategic				2017 Fund From	Additional Project	The second s
Ref. No.	Year	Ranking	Presentation Name	Project Description	Project Justification Benefits	Operating	Staffing	from Project
1	2018	2	Forestry Building new roof	The roof at the Forestry building including the school is original at 25 years old and is at the end of its service life. It is 16,500 sq feet and consists of round river rock ballast over filter fabric and polystyrene insulation. This project proposes to replace the roof membrane and insulation.	To prolong the life of the building. Also as a preventative maintenance measure. As the roof is at the end of it's service life it will start to fail in the next few years and allow water into the building. This project will replace the roof hopefully before it starts to fail.			
2	2017	3	Technology Transformation Program (Multi- year / Carry Forward)	New, modern, connected systems are required in many areas to support District operations. The Application Technology Roadmap which was adopted by Council in 2015 lays out a detailed plan to move forward. At its core the Financial Management system is being replaced. Other connected business systems will follow shortly, within the program timeline.	The organization faces certain risks by relying on aging software with limited support, as its core Finance system. Managers often don't have the information and reports they need making it difficult to plan, control and manage daily operations and major projects. Budgeting and capital planning is difficult and time consuming. Other areas lack systems altogether, relying on workarounds and interim solutions. Many tasks are handled manually. Larger, modern systems will help to integrate and streamline business processes across the organization. Internal operations and customer service will improve. Efficiency gains will stem the tide against ongoing increases in required staff.			Database Admin/Programmer (.5 FTE) , future additional staffing and licensing
3	2017	2	Annual Workstation Upgrades	Workstations are replaced on an ongoing basis by identifying those machines that fall below a set performance standard. Generally it has been the IT Department's goal to provide all areas that require regular use of computers with workstation that are not older than 5 years. Extended warranties on workstation hardware generally expire after 3 years and performance issues and hardware failures start to critically impact staff productivity and IT support time by the 5 year mark	When staff have workstations that are modern and responsive they are more likely to enjoy their work and be productive. It's important that staff who use specialized software have the right hardware to support those resource intensive applications. We are also making use of tablets in the field as the technology is maturing and more internal business tools and apps are available. Laptops will also continue to be needed as more work is done away from the office and meetings are held at various locations away from Municipal Hall.	30,000		
4	2017	2	Large Format Printer/Scanner Replacement	The District's existing large format printer/scanner is 12 years old and has reached the end of life. The organization relies on this equipment to print all large size graphic materials (posters, maps, plans, drawings). These materials are used across the organization for a wide variety of services (e.g.: development review, operational planning, emergency planning, OCP engagement, communications, etc.). The wide format scanner is relied upon for the digitizing large materials for document management, long term storage, development and building permit review.	The organization is dependent on our ability to print large format materials. There is an existing operational budget set aside for the cost of supplies and maintenance of the new equipment. The cost to have materials printed by a third party commercial business is \$6/sqft. The cost of printing in-house with new equipment is under \$0.04/sqft.	19,000		
5	2017	5	Webcam Upgrades	The District's web camera images have been a heavily visited section of the website. In recent years several cameras have failed and there are currently only two that are operational. Requests have been made by members of the public for more local webcams. This was also identified as a potential tactic/action item in the draft Digital Strategy.	Although there are currently only two webcam images, this is still the fourth most heavily accessed section on the District website following job postings and Recreation Centre schedules and activities. On average there are over 350 unique visitors to this section per month. Improving this service will directly impact the public and will potentially lead to more traffic to the District's site, including other sections.	8,000		
6	2018	5	Space Improvements to Public Area of the Library	This project would cover the cost of purchasing new mobile shelving designed for audiovisual materials to improve "findability" and provide the option to reconfigure the shelving layout or open up the space for events.	The current layout of the public area of the library does not make best use of space and does not highlight our popular audiovisual materials. Upgrading to mobile display shelving allows for reconfiguration as needed.			
7	2017	2	RCMP - exterior Camera system upgrade	The RCMP building has an exterior camera system that is 11 years old and in need of upgrading. This is not part of the cell block camera system updated in 2012. 1. There is a blind spot ouside the front door where the RCMP would like to add a new camera so they can see who is standing at the door especially after hours. 2. The current analog DVR is not working properly. It is proposed to replace this with an NVR that allows for the addition of more cameras and the use of higher quality cameras. 3. The system is viewed on one of the two monitors that are both starting to fail. These would be replaced with flat screen high quality monitors.	To upgrade out of date, failing equipment. To improve security at the detachment.	7,500		
8		0	Tantalus Firehall Seismic Upgrade	The structure was constructed in 1978. Multiple previous assessmennts of this facility indicate that the building has settled quite noticeably and the differential settlement has caused distress to the structure. Historical records indicate that the magnitude of differential settlement was in the order of 4 inches in 1990. During a recent site visit with engineers, it was their opinion that the cracks have been getting worse over time and there is a high risk of collapse when an earthquake will hit the Fire Hall. The collapsed structure will block the entrances and will damage and trap the fire trucks inside.	Risk of collapse, putting firefighters at risk and trapping fire trucks inside the building during an emergency.			
9	2017	2	Aerial apparatus scheduled replacement	The fire department's aerial apparatus will be 20 years old in 2017. Insurance Underwriters state current insurance ratings will not be maintained if apparatus age exceeds 20 years. The current 75' apparatus will be replaced with a 100'+ apparatus, which will be required to service the six story buildings that are in the planning stages within the District. The current budget for the replacement of the 75' aerial is sufficient for the purchase of the 100' unit. No budget increases are required for the larger ladder.	For most owners of property within the District, investments in fire department apparatus that are required by Insurance Underwriters are more than offset through favourable insurance premiums.			

Ref. No.	Year	Strategic Ranking	Presentation Name	Project Description	Project Justification Benefits	2017 Fund From Operating	Additional Project Staffing	Service Level Change from Project
10	2017	2	Fire Department Self Contained Breathing Apparatus Scheduled Replacement	Fire Rescue Self Contained Breathing Apparatus Rollover	The current fleet of self contained breathing apparatus is built to an old standard, which is based on an outdated approach to air management (firefighter safety). Equipment meeting newer standards is needed as it will allow our firefighters to utilize procedures that are recognized throughout the industry as modern firefighter safety standards.  40% of existing self contained breathing apparatus cylinders will face a regulatory retirement over the next three years.			
11		0		Alex Munroe Fire Hall in Velleycliffe is a post disaster facility within the District and has received two major seismic upgrades since 2011 to the walls and roof.  The engineer of record had indicated in 2011 that the hose tower had three major structural deficiencies. One was the walls and the other was the roof which have both been retrofitted. During the work in 2012, staff again reviewed the hose tower to pursue a retrofit of the existing tower with no success. The engineer has provided a report that states the cost to retrofit this tower would likely exceed the cost of full replacement. This project proposes to replace the existing tower.	There are three major issues related to the hose tower as it stands - soft story failure, insufficient foundation, high slenderness ratio of masonry walls. The new tower will be a lightweight steel structure built to suit existing conditions. Completing these upgrades will ensure the structure is sound in the case of an earth quake so that it can function as an emergency building as well as a post disaster facility. The tower can also be used for enhanced training of the fire fighters.			
12	2017	2		The roof over the apparatus bay is the largest roof at the firehall and is 15 years old. It is a 2 ply modified bitumen roof and is 4,300 sq ft. The roof has leaked for many years through various penetrations and infact was patched in places 7 years ago. IRC Building Engineers examined the roof in 2014 and determined that there was extensive moisture in the roof through to the roof deck caused by leaks prior to the patching as well as continued leaking since. Given this water damage they recommended to replace the roof as soon as possible. This project is a good value proposition for aligning the roof replacement with the upcoming seismic work.	The moisture over the years has damaged the integrity of the roof – moisture and mold are present in approximately 1/6 of the roof which poses a health and safety risk to the occupants. Allowing the seismic work to be facilitated from the roof and from below lowers construction costs, gives the contractor more flexibility and reduces time. Since we are replacing the east and west walls of the building. It makes sense to tie in the east and west walls into a good roofing membrane. There is considerable ponding on the existing roof and through the re-roofing project, this can be addressed to further reduce the loads on the roof from snow and ponded water.	160,000		
13	2017	1	Tantalus Firehall overhead door replacement	There are 6 overhead doors at the firehall, 5 of which are 30 years old and no longer reliable. This project will replace the doors in conjunction with the siesmic upgrades to the firehall in 2017. This project is outside the scope of work of the seismic upgrades.	This will ensure that the trucks can always exit the building in the case of a fire or other emergency.	60,000		
14	2018	5	Fire Training Centre Search Building	A 2 story 30' x30' search house to replace the current building, which is functional but in need of a new roof.	The fire department's current search building is not large enough for firefighters to develop the skills needed for operating in modern single family homes. The new facility will provide a much greater emphasis on firefighter survival techniques. The department plans to fund much of this work through community donations.			
	2010			A 2 story 30 x30 scarch house to replace the current ballaning, which is functional but in freed of a flew root.				
15	2018	2	Fire Department Pickup Truck Scheduled Replacement	The fire department's 2007 pickup is scheduled for replacement in 2018.	This vehicle is used by chief officers for after hours response as well as transportation as required during office hours. This vehicle is also frequently used by fire inspectors.			
16	2018	2	Fire Department Auto Extrication Equipment	Replacement of fire department auto extrication equipment, which will be 13-14 years old at the time of replacement.	The department's auto extrication equipment is reaching its end of dependable life.  Additionally, changes in automobile manufacturing have led to the need for new equipment.  Modern automobile components are stronger than in the past, so the department's current extrication tools are not always able to manipulate car frames as required.			
17	2017		Fleet Replacement - Animal Control Van (F9211)	Fleet Replacement. Replacing Chevy Express with Ford Transit	Fleet Replacement Bylaw	12,299		
18	2017	5	Resolution Way Compound	Added - Sheet O/S		20,000		
19	2017	Not classified	Incident Command Van Replacement	Replacement of the 2001 Incident Command (IC) van (Gruman work van). The IC Van will be replaced with 23ft trailer and the IC Van will be given to Operations Dept.	The IC Van is not being utilized. A trailor will be a better alternative.			
20	2017	1	Dike Upgrades	The 2017 budget is to prepare for dike upgrades in the upper Judd Slough which is known to be sub-standard by acquiring dike SROW and preparing a shovel-ready design in anticipation of the next round of EMBC grant funding. Subsequent year budgets are placeholders for dike upgrades in Upper Judd Slough, Eagle Run and sea diking in the downtown (assumed to be 2/3rds Provincially/Federally funded). A prioritized project list will be presented in the IFHMP.The budget in 2017 is anticipated to provide a SROW for access to maintain the dike, but is not sufficient to also acquire public access, there would be additional cost for public access.	Acquiring a SROW along the Squamish River dike was mandated as a condition of receiving Provincial funding for original construction of the dike but has not been fulfilled. Several dikes in Squamish are known to be deficient by not having legal access, not reaching the 1:200yr flood height level or having seepage issues. Having legal access will provide the District with the ability to raise and widen the dike with an expanded footprint and also increase the likelihood of receiving Provincial/Federal funding in the future.			
21	2017	4	DCC - R-4 - Pioneer Way Extension	Upgrade Pioneer Way from Queensway to Discovery Way to an arterial road with curbs, sidewalks, bicycle lanes, no parking per the DCC Bylaw.	Upgrade road to improved standard to accommodate ongoing growth in the business park.	10,086		Maintenance Labourer (.19 FTE) \$1,320

Ref. No.	Year	Strategic Ranking	Presentation Name	Project Description	Project Justification Benefits	2017 Fund From Operating	Additional Project Staffing	Service Level Change from Project
							<u> </u>	
					Decreased from prior years to open up envelope funding for alternative transportation initiatives.  As part of the Asset Management Plan, the District also completed a Pavement Management Study			
					which involved a detailed condition assessment and prioritization of all the roads within the District			
				Based on the Public Works Infrastructure Asset Management Plan (endorsed by Council in 2011), the District	and concluded a 20 year replacement plan based on an annual investment of \$1,000,000.00. Based on Council discussion in 2015, this amount has been reduced from \$1M/yr to \$800k/yr. Staff notes			
				should be investing approximately 2% annually in capital asset rehabilitation. This project is to repave roads	that this is not sufficient funding and will increase pavement management costs over the long term			
22	2017	2	Annual Road Reconstruction	annually based on Pavement Management Study performed in 2010.	and result in a greater portion of roads in poor condition.	800,000		
				Road, streetscape, and adjacent park area improvements in keeping with recent Stan Clarke Park				
				improvements. Effort to include re-paving, reconfiguration of parking, curb and gutter, pedestrian crossing	Given the contraints on borrowing and other more critical infrastructure work, along			
23	2017	3	Cleveland - Victoria to Main Streetscape upgrades	bump-outs, landscaping, and additional upgrades in adjacent park area. An old watermain may also be replaced as part of this project which would be funded out of the annual watermain replacement budget.	with uncertainties on Downtown, the recommendation is to move this out two years. The loan authorization for the work expires in 2018 so should be completed by 2017 at latest.			
			1	Transport Canada is requesting all rail crossings to be upgraded by 2021 to improve safety. This project will				
				complete a pre-design in 2016 to provide cost estimates to upgrade rail crossings within Squamish in subsequent years. Budget requests in subsequent years are placeholders until more firm cost estimates are	87% funding can be provided through Transport Canada's Grade Crossing Improvement Program (50%) and CN Rail(37%). Therefore there is a significant opportunity to leverage municipal funds to			
24	2017	1	CN Rail Crossing Safety Improvements	available.	complete significant safety improvements at rail crossings within Squamish with 13 cent dollars.	26,000		
25	2017	2	Streetlight Replacement / Rehabilitation Program	Multi-year budget to replace 10 street lights per year.	Best management practice for asset and risk management.	25,000		
	2017					23,000		
				Multi-year project to convert approximately 60 conventional streetlights to LED per year until all lights are converted.	Business case indicates possible 80% reduction in energy consumption and, at worst, 3 year payback. Possible shorter payback period if BC Hydro rebates are awarded.	27,000		
26	2017	5	Streetlight LED Conversion Program	As identified in the Multi-Medal Transporation Plan, this intersection is a major connection to north Caribaldi				
				As identified in the Multi-Modal Transporation Plan, this intersection is a major connection to north Garibaldi Estates which is experiencing significant growth. This project will add a signal to the intersection and will be				
27	2018	1	DCC - R-15 - Garibaldi/Tantalus Signal	bike and pedestrian friendly.	Improve traffic flow and safety of vehicles, pedestrians and cyclists in this busy intersection.			
				The Multi-Modal Transportation Plan (MMTP) recommends an allowance of \$200,000 annually for the	The average household in Squamish has 3 to 4 bicycles. The MMTP recommends \$3.0 million of			
				development of pedestrian and cycling infrastructure within the District. District Council has indicated a desire	new bicycle routes be constructed by 2031 to establish a comprehensive bicycle network and			
28	2017	3	Active Transportation Improvements	to increase this amount to accelerate improvements to pedestrian and cycling infrastructure. As a result the amount has been increased to \$700k combined for the improvements.	promote/encourage cycling as a safe and efficient mode of transportation. Establishing bicycle routes in the Downtown has been identified as the highest priority area.	200,000		
				This budget will include basic site preparation for new bus shelters that will be installed by a private proponent				
29	2017	3	Bus Shelter Site Preparation	The District's work will include minor paving, site grading, installation of garbage cans to support the new bus stops.	Adequately serviced bus shelters will improve transit ridership.	48,000		
					There is currently a continuous section of bike lane on Tantalus north and south of the missing			
30	2017	3	Tantalus Road Bike Lane	This project will construct a missing section of bike lane on Tantalus Road just north of Harris Rd.	section which pushes cyclists onto the road. Constructing this section will provide a continuous bike lane and improve safety considerably in this area.			
					The District will be able to maintain in both winter and summer all of the primary and connector			
				This unit will have a plow, broom, sander, brine tank and flail mower to be used for trail and sidewalk maintenance	trails plus specific sidewalks. Our exisisting equipment is too light and too wide to fit on the			
31	2017	3	Trails & Sidewalks Maintenance Machine	maintenance	sidewalks and trails. Prior to 2016 the District only maintained the Discovery and Corridor trails.	_		
<u> </u>		J	The State of the s		However in 2016 Council gave direction that the Public Works Department will maintain all			
					The runway requires substantial repairs due to the number of cracks and the condition of the asphalt. The runway has not undergone major repairs since its construction in the 1970's. Minor			
					crack filling, line painting and other repairs have been completed since that time but the condition			
22	2019	2	Airport Punway Pohabilitation	This project would entail repairs and re-ashphalting of the airport rupus	of the runway is worsening. Completing this project would help increase the airport's economic			
32	2018		Airport Runway Rehabilitation	This project would entail repairs and re-ashphalting of the airport runway.	benefits and services.			
					The Asset Management Plan noted that very little information is available on the condition of the			
				Complete Closed Circuit Television and flushing of storm sewers in order to inspect their condition and flush silt	storm sewer system. This project will allow the District to understand the condition of storm sewers in order to determine an appropriate rehabilitation/replacement strategy. This is an			
33	2018	2	Storm Sewer Condition Assessment/Flushing	and sediment.	anticipated outcome of the upcoming Integrated Stormwater Management Plan.			
				The 3rd Avenue pond collects stormwater from most of downtown Squamish. Recently, resident concerns have	Currently untreated stormwater laden with oil and sediment from road runoff are directed into the			
				been raised with respect to the quality of water in the 3rd Avenue pond which ultimately leads to the estuary.	3rd Avenue pond with no treatment. This project will improve stormwater quality in 3rd Avenue			
34	2018	Not classified	3rd Avenue Pond Remediation	This project will complete installation of a new oil/water separator near the inlet to the 3rd Avenue Pond in order to improve water quality and provide environmental enhancement.	pond and ultimately the Bridge Pond by placing a large oil/water separator which will also capture the majority of total suspended solids (TSS) entering the 3rd avenue pond.			
				Each of the offices in the administration trailer at Operations has careet which is now 15 years ald. The arrest				
				Each of the offices in the administration trailer at Operations has carpet which is now 16 years old. The carpet is aged and worn and filthy from constant work boots including workers from the WWTP. This flooring is				
25	2047	2	One analysis of the same of th	unsuitable for such a location and janitors are unable to clean it. Staff are suggesting replacing the carpet with	A resilient floor will be easy to keep clean and sanitized and so provide a safe working	20.000		
35	2017	2	Operations offices new flooring	a resilient flooring that is easy to clean and more suitable for such a location.	environment.	30,000		

Ref. No.	Year	Strategic Ranking	Presentation Name	Project Description	Project Justification Benefits	2017 Fund From Operating	Additional Project Staffing	Service Level Change from Project
					To ensure the comfort of the employees in the building and to reduce energy consumption by			
				The Operations offices are serviced by 3 furnaces and 3 exterior cooling units. All are 18 years old and at the	installing more energy efficient models. The style of heat and cooling system will be determined			
				end of their service life. The roof over the offices is 18 years old and at the end of its service life. It consists of	closer to the the issueing of the tender. The roof will be replaced prior to it failing and will prolong			
36	2018	2	Operations office new HVAC and roof	a single ply flexible membrane consisting of 0.045 in. thick sheet of synthetic rubber which is typical for this type of building. This project will replace all the heat and cooling units as well as the roof.	the life of the building.			
30	2010	2	operations office flew fivac and foor	type of building. This project will replace all the fleat and cooling units as well as the root.				
37	2017	Not classified	Fleet Replacement - Chevrolet 1500 (F9414)	Fleet Replacement	Fleet Replacement Fund Bylaw	5,025		
38	2017	Not classified	Fleet Replacement - F150 (V9080)	Fleet Replacement	Included in Fleet Replacement Fund Bylaw	5,830		
39	2017	Not classified	Fleet Replacement - F150 (V9417)	Fleet Replacement	Included in Fleet Replacement Fund Bylaw	9,370		
40	2017	Not classified	Fleet Replacement - F250 (9081)	Fleet Replacement	Fleet Replacement Fund Bylaw	6,800		
41	2017	Not classified	Fleet Replacement - Tilt Deck Trailer (V9082)	Fleet Replacement	Fleet Replacement Fund Bylaw	6,660		
42	2018	Not classified	Fleet Replacement Ford Ranger (V9416)	Fleet Replacement	Fleet Replacement Fund			
43	2018	Not classified	Fleet Replacement - 628D Mower (V9084	Fleet replacement for Parks department 2007 Jacbosen Turfcat with mower cutting deck, 22 inch cutting rotary and 3 blade deck.				
13	2010	140t classified	Fleet Replacement - 2500 HD Super Cab	and a shade deck.				
44	2018	Not classified	(V9422)	Fleet replacement Roads department 2007 GMC 2500 4x4 extended cab long box pickup.				
45	2018	Not classified	Fleet Replacement - Ranger 4x4 (V9421)	Fleet replacement 2007 Ford Ranger ext. cab 4x4 (9421)				
46	2017	3	Community Wayfinding Project	Development of a comprehensive community wayfinding project. Largely signage that directs visitors to designated destinations in the community.	Will assist in downtown revitalization, tourism and general economic development.	50,000		
10	2017	3	community waymang roject	Community entrance sign at prominent location as the initial effort as part of the Comprehensive Wayfinding	Will assist in downtown revitalization, coansin and Seneral economic development.	30,000		
47	2017	3	Entrance Sign	Project	Council request to incorporate new branding	-		
				There are two large garbage hins and a cardhoard hin in the car park agrees the street from the Adventure				
				There are two large garbage bins and a cardboard bin in the car park across the street from the Adventure Centre used by facility cleaners and tenants. Visitors to the centre often leave garbage around the bins if they				
				are locked or full which of course becomes a bear attractant. In addition the bins are an unsightly welcome to	This will keep garbage away from the bears, remove unsightly garbage bins from view and allow	45.000		
				visitors to the Centre. With the addition of more tenants to the Centre and potentially in the gravel car park,	easy access by Carneys. The enclosure would be designed in consultation with Carneys and the Squamish WildSafeBC Community Coordinator.	15,000		
				production of garbage will increase over the upcoming years. This project proposes to build an enclosure for	Squariisti Wildsafebe Community Coordinator.			
48	2017	5	Adventure Centre garbage bin enclosure	the bins to keep them tidy, easy for Carneys to empty and also to keep the garbage away from the bears.				
100	2017		raventare centre garbage bili enclosure					
				The Adventure Centre is 11 years old. Much of the exterior of the building is fir and pine. All of the				
				exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the				
49	2018	2	Adventure Centre exterior wood staining	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that				
49	2018	2	Adventure Centre exterior wood staining	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the	This will prolong the life of the building as well as ensure it is a spectacular welcome to visitors to Squamish.			
49	2018	2	Adventure Centre exterior wood staining	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that				
49	2018	2	Adventure Centre exterior wood staining	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that	Squamish.  The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service			
49	2018	2	Adventure Centre exterior wood staining	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that	Squamish.  The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly			
49	2018	2	Adventure Centre exterior wood staining	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that	Squamish.  The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in			
49	2018	2	Adventure Centre exterior wood staining	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that	Squamish.  The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly			
49	2018	2	Adventure Centre exterior wood staining  Brennan Park arena ice resurfacer	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that	Squamish.  The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly			
49	2018	2		exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.	Squamish.  The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow	20,350		
		2	Brennan Park arena ice resurfacer	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the	20,350		
		2	Brennan Park arena ice resurfacer	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the	20,350		
		2	Brennan Park arena ice resurfacer	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the	20,350		
		2	Brennan Park arena ice resurfacer	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current	Squamish.  The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the	20,350		
		2	Brennan Park arena ice resurfacer	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone	20,350		
		2	Brennan Park arena ice resurfacer	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only lighting, but also HVAC operations to certain areas, exterior lighting and possibly minimal power required to	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone utilizing the facility, including emergency workers, volunteers, facility staff and members of the	20,350		
		2	Brennan Park arena ice resurfacer	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone	20,350		
		2	Brennan Park arena ice resurfacer replacement	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only lighting, but also HVAC operations to certain areas, exterior lighting and possibly minimal power required to maintain the ice surface. In addition it could provide power to outlets in the meeting rooms for use during an	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone utilizing the facility, including emergency workers, volunteers, facility staff and members of the public. Adding back up power to the ice plant would allow us to maintain a sheet of ice during a	20,350		
50	2017	2	Brennan Park arena ice resurfacer replacement  Brennan Park arena back up generator	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only lighting, but also HVAC operations to certain areas, exterior lighting and possibly minimal power required to maintain the ice surface. In addition it could provide power to outlets in the meeting rooms for use during an emergency. The project costs include new electrical controls and a new enclosure. The existing enclosure is rotten.	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone utilizing the facility, including emergency workers, volunteers, facility staff and members of the public. Adding back up power to the ice plant would allow us to maintain a sheet of ice during a lengthy power outage. The outage in late August 2015 caused four ice arenas in the lower			
50	2017	2	Brennan Park arena ice resurfacer replacement  Brennan Park arena back up generator	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only lighting, but also HVAC operations to certain areas, exterior lighting and possibly minimal power required to maintain the ice surface. In addition it could provide power to outlets in the meeting rooms for use during an emergency. The project costs include new electrical controls and a new enclosure. The existing enclosure is rotten.  The existing motor controls for the ice making equipment are a mix of original and new technology. This makes	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone utilizing the facility, including emergency workers, volunteers, facility staff and members of the public. Adding back up power to the ice plant would allow us to maintain a sheet of ice during a lengthy power outage. The outage in late August 2015 caused four ice arenas in the lower			
50	2017	2	Brennan Park arena ice resurfacer replacement  Brennan Park arena back up generator	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only lighting, but also HVAC operations to certain areas, exterior lighting and possibly minimal power required to maintain the ice surface. In addition it could provide power to outlets in the meeting rooms for use during an emergency. The project costs include new electrical controls and a new enclosure. The existing enclosure is rotten.	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone utilizing the facility, including emergency workers, volunteers, facility staff and members of the public. Adding back up power to the ice plant would allow us to maintain a sheet of ice during a lengthy power outage. The outage in late August 2015 caused four ice arenas in the lower			
50	2017	2	Brennan Park arena ice resurfacer replacement  Brennan Park arena back up generator	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only lighting, but also HVAC operations to certain areas, exterior lighting and possibly minimal power required to maintain the ice surface. In addition it could provide power to outlets in the meeting rooms for use during an emergency. The project costs include new electrical controls and a new enclosure. The existing enclosure is rotten.  The existing motor controls for the ice making equipment are a mix of original and new technology. This makes routine maintenance and operation of the ice plant difficult. In the past 3 years we have had emergency situations where the plant has quit operating and many hours have been spent trying to re start it. The cause has always been a failed piece of orginal control equipment. Sourcing replacement parts has been very difficult.	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone utilizing the facility, including emergency workers, volunteers, facility staff and members of the public. Adding back up power to the ice plant would allow us to maintain a sheet of ice during a lengthy power outage. The outage in late August 2015 caused four ice arenas in the lower mainland to lose ice, greatly increasing costs and impacting the public.  Upgrading the plant controls will allow for easier and more efficient operation and would include			
50	2017	2	Brennan Park arena ice resurfacer replacement  Brennan Park arena back up generator replacement  Brennan Park arena motor control centre	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only lighting, but also HVAC operations to certain areas, exterior lighting and possibly minimal power required to maintain the ice surface. In addition it could provide power to outlets in the meeting rooms for use during an emergency. The project costs include new electrical controls and a new enclosure. The existing enclosure is rotten.  The existing motor controls for the ice making equipment are a mix of original and new technology. This makes routine maintenance and operation of the ice plant difficult. In the past 3 years we have had emergency situations where the plant has quit operating and many hours have been spent trying to re start it. The cause has always been a failed piece of original control equipment. Sourcing replacement parts has been very difficult An upgraded control centre would modernize our entire ammonia refrigeration control system and would	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone utilizing the facility, including emergency workers, volunteers, facility staff and members of the public. Adding back up power to the ice plant would allow us to maintain a sheet of ice during a lengthy power outage. The outage in late August 2015 caused four ice arenas in the lower mainland to lose ice, greatly increasing costs and impacting the public.  Upgrading the plant controls will allow for easier and more efficient operation and would include extra space for possible future arenas. Improved reliability would ensure continued use of the ice			
50	2017	2	Brennan Park arena ice resurfacer replacement  Brennan Park arena back up generator replacement  Brennan Park arena motor control centre upgrades (arena slab carryover)	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only lighting, but also HVAC operations to certain areas, exterior lighting and possibly minimal power required to maintain the ice surface. In addition it could provide power to outlets in the meeting rooms for use during an emergency. The project costs include new electrical controls and a new enclosure. The existing enclosure is rotten.  The existing motor controls for the ice making equipment are a mix of original and new technology. This makes routine maintenance and operation of the ice plant difficult. In the past 3 years we have had emergency situations where the plant has quit operating and many hours have been spent trying to re start it. The cause has always been a failed piece of orginal control equipment. Sourcing replacement parts has been very difficult.	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone utilizing the facility, including emergency workers, volunteers, facility staff and members of the public. Adding back up power to the ice plant would allow us to maintain a sheet of ice during a lengthy power outage. The outage in late August 2015 caused four ice arenas in the lower mainland to lose ice, greatly increasing costs and impacting the public.  Upgrading the plant controls will allow for easier and more efficient operation and would include			
50	2017	2	Brennan Park arena ice resurfacer replacement  Brennan Park arena back up generator replacement  Brennan Park arena motor control centre	exterior wood was cleaned and restained in 2014. The nature of the stain as well as the exposure of the building requires the stain to be re applied every 2 - 4 years. This project also proposes to remove the sap that has seaped out of the exposed wood on the inside of the building in particular as the wood has dried.  This project proposes to replace the electric ice resurfacer with a more efficient, higher capacity unit that is easier to maintain. The existing machine would be traded in for a new machine.  The current back up generator is 37 years old and is past it's service life. This project proposes to replace the current 15kw natural gas generator with a more powerful unit for use during power outages. The current unit can only supply minimal lighting in the community centre and arena. A larger unit will provide not only lighting, but also HVAC operations to certain areas, exterior lighting and possibly minimal power required to maintain the ice surface. In addition it could provide power to outlets in the meeting rooms for use during an emergency. The project costs include new electrical controls and a new enclosure. The existing enclosure is rotten.  The existing motor controls for the ice making equipment are a mix of original and new technology. This makes routine maintenance and operation of the ice plant difficult. In the past 3 years we have had emergency situations where the plant has quit operating and many hours have been spent trying to re start it. The cause has always been a failed piece of original control equipment. Sourcing replacement parts has been very difficult An upgraded control centre would modernize our entire ammonia refrigeration control system and would	The current electric unit is 7 seasons old and is becoming more costly to maintain. In the past 4 years of service we have had average annual maintenance charges of \$6,000 for routine service and just over \$2,500 in emergency service. Certain options of the unit no longer work and costly fixes seem to be temporary. In addition the battery and charging unit are due to replacement in 2017 at an expected cost of \$20,000. A new electric unit with fewer electronic systems will greatly improve the reliability of the machine. Higher capacity in the same machine footprint would allow for back to back cleans without dumping and refill delays if there is an ice surface added to the facility.  The facility is now recognized as an Emergency Reception Area for the community. Improving the lighting and having operating air units and power will improve safety and comfort for anyone utilizing the facility, including emergency workers, volunteers, facility staff and members of the public. Adding back up power to the ice plant would allow us to maintain a sheet of ice during a lengthy power outage. The outage in late August 2015 caused four ice arenas in the lower mainland to lose ice, greatly increasing costs and impacting the public.  Upgrading the plant controls will allow for easier and more efficient operation and would include extra space for possible future arenas. Improved reliability would ensure continued use of the ice			

		Strategic				2017 Fund From	Additional Project	Service Level Change
Ref. No.	Year	Ranking	Presentation Name	Project Description	Project Justification Benefits	Operating	Staffing	from Project
				In order to allow for increased use of the facility while maintaining security in the open floor plan design at the centre, security gates need to be installed. The gates would be designed and positioned to stop access into the café cash area/coffee bar and the administration offices at the south end of the building when the building is				
54	2017	6	Senior Centre security gates	open to the general public, but has limited staffing.	of staff in these areas after hours.	25,000		
55	2017	2	Brennan Park floor machine	A walk behind floor machine allows staff to easily and efficiently scrub and clean our extensive collection of large surface floors. The current machine is 15 years old and maintenance and servicing has increased dramatically in recent years. For four weeks this year, and six weeks last year, the machine was out of service while we waited for contractors to find and install parts.	Our service contractor has advised they will no longer be able to provide service on the machine in 2017 due to discontinued parts. Without an adequate floor machine staff will need to hand mop the floors.	17,000		
56	2017	2	Brennan Park Arena new strip drain	The ice resurfacer bay floor is used not only as a garage bay for the resurfacer when the ice isn't being cleaned, but also as a vehicle maintenance work area for both resurfacers and our ice edger. After decades of use the floor has become uneven and even developed ruts where the studded tires have worn down the concrete surface. Water pools in the ruts making it uncomfortable when staff have to lay on the floor to change the blades, grease the unit of perform any number of preventive maintenance duties. Dirt and debris are brought in from outside when the ice resurfacer dumps the snow — this debris frequently ends up on the ice and can be a safety concern if it is not noticed by staff.	The project would involve installing 2 driveway trenches on each side of the bay and 2 at the back of the bay before accessing the ice. Resurfacing of the bay would be completed with a epoxy compound designed for workshops/garages. These improvements would make the area safer, more comfortable and suitable for the current use. This would occur during annual shutdown in the Spring.	16,500		
57	2017	2	Replacement Infield Groomer	Replacement of infield groomer for ball fields	Existing groomer is at end of life	16,500		
58	2017	2	Replace greenhouse	Existing greenhouse is in poor repair and on Ministry of Highways property. The unit needs to be replaced in a different location. Initial idea is to relocate to the public works yard and potentially use a heat transfer system using sewage heat from the WWTP to heat the greenhouse. 2017 will complete an initial feasibility review and 2018 will construct the greenhouse.	Costs are kept down for our horticulture program by having a greenhouse. A new green house will be more efficient and cost effective. Currently the District pays \$\$\$\$ to heat the green house.			
			Roof Replacement - Brennen Park Pump	2000 Mill obligated the greenhouse.	active constitution and cost concentral contents of the state of pays yayay to meat the great mouse.			
59	2017	2	House	Replacing roof.  Bearproof storage cashe. Site improvements.	Roof at Brennen Park pump house has reached end of life and requires replacement.  Risk. Bear Aware Program. Public health and safety. Optics.	5,000		
60	2017	1	Campground Regulatory Improvements	bearproof storage casile. Site improvements.	Nisk. Deal Aware Program. Public health and safety. Optics.	10000		
61	2018	2	Brennan Park Arena Insulation	The original wall insulation (plastic batt and donnaconna boards) is damaged and falling apart. Stains, rips and fading detract from the newly upgraded facility. The ceiling foil was a first attempt at a low emmisivity ceiling that didn't work as promised. It is not vapour tight and damage by pucks has reduced it to simply being silver tinsel. The project would involve skinning the North, East and South walls with a reflective product to improve aesthetics and provide a puck proof surface around the perimeter. The arena ceiling would be covered with rigid insulation designed to reduce humidity and radiant heat over the ice and improve lighting levels and acoustics.	Improving the quality of the air in the ice rink by reducing radiant heat and humidity will allow for even better quality ice at lower energy costs. Upgrading the ceiling and walls will reduce refrigeration costs. The improved surfaces around and over the rink could also allow for a safe reduction in lighting levels during public/family skate programs.			
62	2018	5	Baseball Field Backstop & Dugout Replacement	New dugout field #2 New backstop and dugouts required at field #3. New backstop and dugouts required for field #6. Estimated budget required = \$100,000. 3 year plan for replacement	Equipment at end of useful life and is a hazard			
63	2017	6	Dentville community park	Design and construction of a destination park near the current skate bowl per the DCC bylaw and agreement with the developer of 38684 Brittania Ave.	Neighborhood need, master plan recommended, supported by Council	66,960		
64	2017	2	Brennen Park Electrical Shed Repairs	Replacement of siding and roof.	Siding and roof has reached end of useful life.	10,000		
65	2017	5	Replacement of Parks Fertilizer Spreader	300 Liter fertilizer spreader, 3 point hitch.	Existing equipment at end of life and requires constant maintenance.	10,000		
66	2018	6	Tourism access/Trailhead Improvements	A detailed review is planned in early 2018 as part of the Parking Strategy Implementation project that will identify locations and work recommended for trailhead improvements at popular trails and tourist destinations. This project will complete the physical work to make those improvements including adding additional parking, adding bathrooms, garbage cans, signage, etc.	Reduce congestion and parking difficulties at popular areas as well as reduce litter and waste generated at the sites by adding facilities such as bathrooms and garbage cans.			
67	2018	4	Cemetery Over-excavation	Need to remove rocky, gravelly material from unused cemetery portions and replace with soil more condusive to full earth burial and/or cremation.	Current cemetery area filling up. 80 plots left. Need to open up new area for burial.			
68	2017	4	SODC - R-20 - Peninsula Main Road - Arterial Standard	Construction of a looped road from the peninsula boundary to the Oceanfront Park.	Improved access to support peninsula wide development and access to the Oceanfront Park.			

Ref. No.	Year	Strategic Ranking	Presentation Name	Project Description	Project Justification Benefits	2017 Fund From Operating	Additional Project Staffing	Service Level Change from Project
69	2017	4		Construction of storm sewers on peninsula that will service SODC development as well as other future development on peninsula	Allows future development of peninsula.	4,810		
70	2017	4	SODC - DCC D-13 - Peninsula Treatment Wetland at Mamquam Blind Channel	Required as part of SODC development.	Required as part of SODC development.	2,600		
71	2017	4	SODC - DCC D-14 - Peninsula Treatment Wetland at Road 'O'	Stormwater treatment wetland required as part of the SODC development.	Improved environmental values incorporated into SODC development scheme.	2,600		
72	2018	4	SODC - DCC P-17 - Oceanfront Boardwalk A & B	Construction of an oceanfront boardwalk at the SODC lands as a public amenity.	Recreational amenity for public use.			